231 South La Salle Street Chicago

January 13, 1938

Mr. R. E. Galbreath, Supt. Wisconsin Steel Company Benham, Kentucky

Dear Sir:

Every once in a while we get a complaint on coal you are shipping for our account which leads me to believe that your coal mine is just like any other and once in a while something goes wrong with the screens without anyone discovering it until the coal gets into the customer's yard.

I am referring particularly to L&N 60752, furnace coal, shipped Sherril Ice & Fuel Company, Valdese, North Carolina on December 24th and L&N 28346, furnace coal, shipped Mountain Ice & Coal Company, Morganton, North Carolina on December 28th, both for the account of Old Dominion Coal Iron and Coke Corporation. Both customers seem to think that some serious mistake has been made as the coal is a mixture of 5x3 and everything else down and a lot of 3x2 and some straight screenings.

If you have any way of investigating the loading at this late date I wish you would do so, but if you cannot account for it say so. I am wondering if the change in the size of the screens which you made some months back in order to make the same sizes as are produced at our mine #30 and #31 has made any marked difference in the preparation of the coal for better or worse.

Very truly yours,

1110 115738 2803 R.L. 1-17-38 2013 1-17-38

5 X 3 Egg Cone both Cans