

New
4

E6

12-8-59 ✓

To Rmck:

Motors and building equipment have been inspected for month of November.

Water samples were taken.

These things were found defective.

- 2 hrs - Buckingham - No overheat protection on 1 hr.
- 1 hr - Price Supply House
- 2 hrs - Price Shop #2
- 3 hrs - Price Shop #1
- 1 hr - Price Man Station #1-
- 2 hrs - Price Car Shop #1

These things were corrected by W. J. and J. D.

Circulating motor at Club House - Thermostat not working. This reported to Oscar Smith. ✓

Other units found working normally.

Forest Spausome