

INLAND STEEL COMPANY

WHEELWRIGHT, KENTUCKY

T-5

6 February 1956

To: G. F. Leatherman
From: H. O. Zimmerman


At the staff meeting Saturday morning a discussion was held regarding the failure of the cable which disrupted our telephone service.

It was pointed out that this was due to the lack of drainage from the conduit and manholes at the rear of the office, store and colored recreation buildings.

This is not the first time we have had difficulty in this section of our telephone system due to the lack of drainage, and I feel some steps should be made to correct it to prevent future failures from this cause.

It was decided that you would look into this matter to see what could be done to provide proper drainage. You may call on Joe Persino and Rodney McKinney for any help you need.

I would appreciate a report from you as to what steps you feel can be taken to correct the condition.


Manager Coal Properties

HOZimmerman-kf

cc: JPeraino
RIMcKinney ✓