


• STRIKING HEAD AGAINST LOW PLACE,
ROOF OR CROSS TIMBERS.




RAN UNDER LOW ROOF. PINNED AGAINST
TOP OF MOTOR.



CRUSHED BY FALL OF ENTRY SLATE.




HIGH SPEED. MOTOR WRECKED. CRUSHED
AGAINST TOP.



BACK POLING. TROLLEY CAME OFF.
GRABBED. MISSED. FELL OUT.

! KILLED



JUMPED OUT IN FRONT OF MOTOR
WHEN CONTROLLER FLASHED.




DRAGGED OVER TOP OF MOTOR, IN LOW
TOP, BY REEL CABLE.

ARE




COLLIDED WITH TRIP OF PUSHED CARS
GOING IN OPPOSITE DIRECTION.

MOTOR MEN



ELECTROCUTED. CONTACTED TROLLEY.



WORKING ON SAND PIPE AND CAUGHT
BY TIGHT PLACE ON RIB.