

WATCH YOUR DRAW SLATE



WORK IT OFF YOUR CUT OF COAL
BEFORE IT HAS A CHANCE TO FALL AND
PIN YOU AGAINST THE CAR YOU MAY BE
LOADING. CAR, POSTS AND GOB
MAY PREVENT YOUR ESCAPE.

SOUND YOUR TOP OFTEN
WATCH YOUR TOP ALWAYS