

Total Low - B Seam = Mach
 Mach + B Seam + Co Coal + ~~Coal~~ = Total
 Total - Cr. Coal = In Bin

TONNAGE STATEMENT

Date

Nov. 1946

Date	Quit	Mach.	"B" Seam	Co. Coal	No. Check	Coal "B"	Total	Cr. Coal	In Bin
1		17934	46636	—	185	3744	68499	97	68407
2		13750	35476	97	115	2719	57107	270	50837
3		31184	87062	92	300	5963	119601	362	119139 O.K.
4		14088	40631	73	317	2373	57387	39	57343
5		12862	35799	—	79	2789	51049	45	50984
6		14135	41851	—	89	2517	58692	349	58343
7		17147	44179	—	247	4158	63731	—	63731
8		13978	42252	—	273	2691	59144	125	59019
9		17004	34484	33	212	3459	60192	37	50153
10		115448	321258	148	1517	71400	459771	957	458814 O.K.
11		15480	40779	—	141	3715	60075	44	60031
12		13910	41344	—	264	1710	57778	371	57407
13		15104	40192	64	100	1661	57241	153	57068
14		<i>Idle</i>							
15		15693	39352	195	74	4090	59404	33	59371
16		<i>Idle</i>							
17		175635	483975	407	7096	3686	694199	1508	692691 O.K.
18		14596	38088	—	114	6078	58876	96	58730
19		13079	40536	—	100	3459	57174	37	57137
20		14873	41300	62	133	3479	59247	81	59166
21		14543	39139	—	140	3086	57008	47	56961
22		17975	39303	101	305	2807	60491	78	60413
23		13001	33859	—	86	2840	49787	123	49664
24		263703	716300	570	7974	53785	1037337	1970	1035367
25		14612	39719	83	97	3713	57724	40	57684
26		14992	42263	23	334	3020	60632	182	60450
27		16269	43252	—	244	3625	63591	263	63328
28		15797	44346	—	61	2909	63113	219	62894
29		18717	39779	—	188	2981	60665	78	60587
30		13472	35374	194	99	2647	51986	145	51841
31									
Total	Cwts.	357762	960034	870	3997	72380	17395043	2897	1392146
Total	Tons	1788810	4800170	4350	19985	361900	16975215	14485	6960730

+ 10260 - 10260
 1799070 4789910