\$ 210.63

\$ 216.27

5.64

To: E. M. Pace From: R. I. McKinney

Re: Monthly Report - Buildings and Grounds Department - January, 1963

Room and Bath Additions None		
Furnace Inst	allations	Acct. 51-182
	Floor Furnace (completed)(replacement) Labor \$142.84 Mtls. \$81.69	\$223.53
Ho. No. 390	Wall Furnace (not complete) (new) Labor \$ 93.14 Mtls. \$ 8.46	Acct. 51-182 \$101.60
Misc. Jobs		
Apt. A-9-2	Sink Top installation (completed) Labor \$23.94 Mtls. \$124.70	Acct. 51-181 \$148.64
Apt. A-9-2&3	Repairs prior to painting (completed) Labor \$142.14 Mtls. \$268.89	Acct 51-181 \$411.03
Ho. No. 29 R	epairs prior to painting (completed) Labor \$ 23.64 Mtls. \$ 41.81	Acct. 51-181 \$ 65.45
Ho. No. 213	Refloor kitchen and bath (completed) Labor \$141.84 Mtls. \$ 67.68	Acct. 51-181 \$209.52
Ho. No. 3952	Base cabinets w/sink top (complete) Labor \$ 71.22 Mtls. \$279.84	Acet. 51-181 \$351.06
Ho. No. 3952	Clothes closet (complete) Labor 47.28 Mtls. \$ 32.68	Acct. 51-181 \$ 79.96
Ho. No. 395€	Flooring 1 room (complete) Prev. Labor \$47.28 Prev. Mtls. \$ 52.83 Jan. Labor Jan. Mtls. 4.40	
	Completed cost	\$104.51
Ho. No. 3952	Repairs prior to painting Prev. Labor \$141.84 Prev. Mtls. \$57.7 Jan. Labor 45.86 Jan. Mtls. 67.7	
	Completed cost	\$313.16
Safety Turkey Boards - Repairs and Painting		

Acet. 0-91-1851

Acct. 0-91-3851

Cost to date

Labor

Mtls.