Form W.E. Acct. 22

INLAND STEEL COMPANY

Fo.b. 7 1956
- Mac : 1 10 11 1
FROM: RRT
The following repairs are requested by
Troy Hemphill House No. 249
COMMODE LEaking behind
each time it's flushed -
sweat was only thing leading.
also needs toilet sout
Approved Superintendent of Buildings and Grounds
- Ci
Work Completed
ton new seat, signed Black
Foreman