

INLAND STEEL COMPANY
BUILDING & GROUNDS DEPARTMENT

Project Cost Sheet

Project No. See 253. Acct. No. 51-181 Sheet No. _____

Description Floor Furnace Gen Repair Date Started APR 16 1957

Date	Materials Used	Cost Mtls.	✓	Cost Labor	✓	Total	Remarks
Apr 16	Floor Furnace	129 40					
	2x8-12 ft	16 @ 14					
	2x4-16 ft 5 ft	55 @ 14					
	Metal Corner Brak	40 @ 7					
	Rock lath	96 @ .42					
17	1" Poplar	40 @ 20					
	2/8 x 6/8 floor			9 60			
	lock & Bulls			2 85			
	2x4x16	11 @ 14		1 54			
19	Plaster	5 @ 90					
	Carpenters	6 @ 21.4		129 84			
19	Plaster			41 64			
21	"	4 - 90		3 60			
				46 85		151 48	198 33