



THIS MACHINE MAN WAS FATALLY INJURED WHEN HE CRAWLED OVER THE CUTTER BAR, WHILE THE CHAIN WAS IN MOTION. YOU SAY SUICIDE? NO MORE SO THAN CUTTING PLACES UNDER LOOSE TOP. PLACES THAT SHOULD BE LEFT DOWN UNTIL THEY ARE SAFE, NO MORE SO THAN THE DANGERS YOU CAN LET YOURSELF INTO IF YOU DO NOT OBSERVE THE RULES OF TRAMMING AND HANDLING YOUR MACHINE AT THE FACE.