

393

JOB TICKET

JOB DESCRIPTION

REPAIRS TO HOUSE #393
FOR RENT

MATERIALS USED

COST

REPAIRS TO BATH ROOM
REMOVING OLD ROOF
REMOVING OLD PLASTER
WHERE ROOF AND CEILING
AND WALLS HAVE ROTTED

TIME

HOURS

8

Date 5-27-69

EMPLOYEE:

Curt Herron

HOUSE NO. 393