

## HOUSE RECORD

HOUSE-Apmt.	No. Rooms	Bath <span style="float: right;">/</span>	Storage Room	FURNACE - Type <i>Floor 706-4</i>	Modernized Kitchens
No. <b>169</b>	<i>5</i>	Toilet	<i>yes</i>	Date Installed <i>2-13-58</i>	<i>SINK UNIT +</i>
				Serial No. <i>90 3283</i>	<i>Cabinets</i>

DATE	Additions - Painting - General Repairs, etc.	COST		
		Labor	Materials	Total
<i>Jan. 1964</i>	<i>Ticket work</i>		<i>2 30</i>	
<i>1964</i>	<i>Paint Reserve 2794 <sup>3-50 Doors</sup> 12 = 291 yds @ .26</i>	<i>75 66</i>		
<i>aug "</i>	<i>Ticket work sink rep.</i>		<i>19 5</i>	
<i>Nov. "</i>	<i>" " flush tank rep.</i>		<i>90</i>	
<i>Dec "</i>	<i>" " " " "</i>		<i>3 10</i>	
<i>July 1965</i>	<i>Special job - Repair front porch</i>	<i>25 64</i>	<i>20 06</i>	<i>45 70</i>
<i>Mar 1966</i>	<i>Special job step repair</i>	<i>51 28</i>	<i>6 01</i>	<i>57 29</i>
<i>May "</i>	<i>Ticket step rail rep.</i>		<i>20 6</i>	
<i>July "</i>	<i>" flush tank rep.</i>		<i>43</i>	
	<u><i>G. O. Vitatoe</i></u>			
<i>2/12/69</i>	<i>5 gal. Latex Paint</i>			
<i>7/2/69</i>	<i>1 gal. Enamel Paint</i>			
<i>4/30/71</i>	<i>2 gal Outside paint</i>			
<i>6/14/71</i>	<i>1 " " "</i>			
<i>11-18-74</i>	<i>2 gal inside paint</i>			
<i>4-7-76</i>	<i>5 <del>4</del> gallon inside paint</i>			

Remarks:

Reference No.

**169**